

Weep holes must be provided for the draining of water behind the retaining wall.

tm	Transport Malta				
Roads & Infrastructure Directorate					

ROAD CONSTRUCTION DETAILS

Brickwork, Blockwork and Stonework

k	Rev:	Remarks:	Drawn:	Date:
	Α	Issued drawing.		Dec. 2003
	В	Change logo to TM	E. Farrugia	April 2014

Title:

MASONRY RETAINING WALLS WITH PRECAST CONCRETE RUBBLE PANELS 5m HEIGHT

Drawing No.:

RCD 2400/08